

▶1:Transmission

Log Mag


10.0 dB/

Ref

0.00 dB

C?



▷2:Off





Start 0.300 MHz

Stop 90.000 MHz

1:Mkr (MHz)	dB	2:Mkr (MHz)	dB
1> 40.0000	-63.126		
2: 50.0000	-0.895		




Start 0.300 MHz			Stop 1 000.000 MHz		
1:Mkr (MHz)	dB		2:Mkr (MHz)	dB	
1> 40.0000	-61.635		1: 40.0000	-18.553	
2: 50.0000	-1.713		2: 50.0000	-17.347	
3: 550.0000	-0.171		3: 550.0000	-19.784	
4: 870.0000	-0.334		4> 870.0000	-22.872	



1:Mkr (MHz) dB			2:Mkr (MHz) dB		
1>	40.0000	-1.048	1:	40.0000	-18.160
2:	50.0000	-63.930	2>	50.0000	-19.378

▶1:Transmission Log Mag 10.0 dB/ Ref 0.00 dB C

▷2:Off



Start 0.300 MHz

Stop 1 000.000 MHz

1:Mkr (MHz)	dB	2:Mkr (MHz)	dB
1> 40.0000	-1.356		
2: 50.0000	-61.717		